

Measure DC loop resistance

Use **Procedure 7** to measure DC loop resistance.

Procedure 7

Measure DC loop resistance by using standard procedures.

Note: The DC loop resistance limit of 175 ohm should be reduced by 1 ohm for each one percent of the total loop that is aerial cable.

Meridian 1

Digital telephone line engineering

© 1989,1994 Northern Telecom

All rights reserved

Information is subject to change without notice.

Northern Telecom reserves the right to make changes in design or components as progress in engineering and manufacturing may warrant. This equipment has been tested and found to comply with the limits for a Class A digital device pursuant to Part 15 of the FCC rules.

SL-1 and Meridian 1 are trademarks of Northern Telecom.

Publication number: 553-2201-180

Document release: Standard 3.0

Date: December 1994

Printed in the United States of America